

ABSTRACT

An optic fiber must be properly aligned with a laser in order to maximize optical power transmission. The fiber is aligned with a holder by welding the fiber to the holder. A screen is placed between the welds and the laser in order to protect the laser from weld splatter.

909853_1.DOC